

**Sale Name:** September 26, 2025 - Friday Major Automotive & Recreational Live & Timed Auction

**LOT 133 - 2008 Ford F-150 4x4 XLT 4dr SuperCab Styleside 5.5 ft. SB**



**VIN** 1FTRX14W18FA73409

**Year** 2008

**Make** Ford

**Model** F-150

**Trim Level** 4x4 XLT 4dr SuperCab Styleside 5.5 ft. SB

**Body Subtype** Extended Cab

**Engine** 4.6L V8 248hp 294ft. lbs.

**Transmission** 4-Speed Automatic

**Odometer** 294,718

**Odo Type** KM

**Declaration** Engine Light On

**Comments** Interior - Animal hair present throughout vehicle, headliner/seats/carpet stains, seats tears. Exterior - Multiple scratches/paint chips, front left fender paint peeling/rust, front left door paint bubbling/rust/inner door rust, rear left door paint bubbling/rust, rear left fender rust/holes/trim piece screwed into fender/repainted, rear bumper dents/rust, tail gate red, right rear fender paint peeling/rust, front right door paint bubbling/rust, front right fender paint peeling/rust, front bumper rust, windshield chips/chip cracks. \*Rear left fender holes, dip stick tube rusted on inside and unable to get dip stick back in/covered with duck tape. FEATURES - HITCH, TILT, CRUISE CONTROL, MANUAL SEATS, PWR MIRRORS, PWR LOCKS, PWR WINDOWS, HEAT FUNCTIONING, AC FUNCTIONING, HANDS FREE CALLING, CD PLAYER

**Location** Fredericton NB - Jardine

**Tires** Front 5/32, rear 2/32

**Sales Status** Red Light - Sold AS IS

**Plate Date (Jardine)** 03/26

**Plate Number (Jardine)** CMZ 783

**MVI (Jardine)** 10/26

## Description

CLEAN CARFAX,

Vehicle loud possible exhaust leak, rear left fender holes, dip stick tube rusted on inside and unable to get dip stick back in/covered with duck tape

**Vin** 1FTRX14W18FA73409

**Year** 2008

**Make** Ford

**Model** F-150

**Trim** 4x4 XLT 4dr SuperCab Styleside 5.5 ft. SB, Extended Cab

**Engine** 4.6L V8 248hp 294ft. lbs.

**Transmission** 4-Speed Automatic

**Odometer:** 294,718, KM

**Declaration** Engine Light On

**Location** Fredericton NB - Jardine

**Comments** Interior - Animal hair present throughout vehicle, headliner/seats/carpet stains, seats tears. Exterior - Multiple scratches/paint chips, front left fender paint peeling/rust, front left door paint bubbling/rust/inner door rust, rear left door paint bubbling/rust, rear left fender rust/holes/trim piece screwed into fender/repainted, rear bumper dents/rust, tail gate red, right rear fender paint peeling/rust, front right door paint bubbling/rust, front right fender paint peeling/rust, front bumper rust, windshield chips/chip cracks. \*Rear left fender holes, dip stick tube rusted on inside and unable to get dip stick back in/covered with duck tape. FEATURES - HITCH, TILT, CRUISE CONTROL, MANUAL SEATS, PWR MIRRORS, PWR LOCKS, PWR WINDOWS, HEAT FUNCTIONING, AC FUNCTIONING, HANDS FREE CALLING, CD PLAYER

**In Yard** Yes

**Tires** Front 5/32, rear 2/32

**Sales Status** Red Light - Sold AS IS

**Plate Date** 03/26

**Plate Number** CMZ 783

**MVI** 10/26

**Quantity:** 1



<https://www.maauctions.com/>