Sale Name: September 26, 2025 - Friday Major Automotive & Recreational Live & Timed Auction

LOT 174 - 2017 Chevrolet Silverado 1500 4x4 LT 4dr Double Cab 6.5 ft. SB



VIN 1GCVKREC1HZ395952

Year 2017

Make Chevrolet

Model Silverado 1500

Trim Level 4x4 LT 4dr Double Cab 6.5 ft. SB

Body Subtype Extended Cab

Engine EcoTec3 5.3L V8 355hp 383ft. lbs.

Transmission 6-Speed Shiftable Automatic w/Overdrive

Odometer 150,343

Odo Type KM

Color White

Comments Interior - Headliner/seats/floor stains, glass shards throughout vehicle. Exterior Front left fender scratches/dents, left rocker rust, front left door scratches/paint chips/doorsill rust, rear left door scratches/paint chips/doorsill dents, left rear fender scratches/paint chips/dents, rear bumper scratches, tailgate rust specs/paint chips, right rear fender taillight broken/scratches/paint chips, right rear cab corner rust, right rear door scratches/paint chips/rust specs, front right door rust specs/paint chips/doorsill dents, front right fender rust specs/paint chips, front bumper paint chips/rusr specs, hood paint chips, windshield shattered HITCH, ALUM RIMS, HEATED MIRRORS, HEATED SEATS, TILT, INFOTAINMENT SYSTEM, CRUISE CONTROL, MANUAL SEATS, PWR SEATS, PWR MIRRORS, PWR LOCKS, PWR WINDOWSHEAT FUNCTIONING, AC FUNCTIONINGBACKUP CAMERA, BLUETOOTH, SUBSCRIPTION BASED SATELLITE RADIO, CD PLAYER

Unit No. TDFV158615

Location Fredericton NB - Jardine

Tires Front 16/32 265/65/18, rear 3/32 265/65/18

Sales Status Green Light MVI (Jardine) 03/25

Description

BANK REPOSSESSION

CARFAX- OTHER DAMAGE \$2,722.00.

Windshield shattered

Vin 1GCVKREC1HZ395952
Year 2017
Make Chevrolet
Model Silverado 1500
Trim 4x4 LT 4dr Double Cab 6.5 ft. SB, Extended Cab
Engine EcoTec3 5.3L V8 355hp 383ft. lbs.
Transmission 6-Speed Shiftable Automatic w/Overdrive

Odometer: 150,343, KM

Color White

Location Fredericton NB - Jardine

Comments Interior - Headliner/seats/floor stains, glass shards throughout vehicle. Exterior Front left fender scratches/dents, left rocker rust, front left door scratches/paint chips/doorsill rust, rear left door scratches/paint chips/doorsill dents, left rear fender scratches/paint chips/dents, rear bumper scratches, tailgate rust specs/paint chips, righr rear fender taillight broken/scratches/paint chips, righr rear cab corner rust, right rear door scratches/paint chips/rust specs, front right door rust specs/paint chips/doorsill dents, front right fender rust specs/paint chips, front bumper paint chips/rusr specs, hood paint chips, windshield shattered HITCH, ALUM RIMS, HEATED MIRRORS, HEATED SEATS, TILT, INFOTAINMENT SYSTEM, CRUISE CONTROL, MANUAL SEATS, PWR SEATS, PWR MIRRORS, PWR LOCKS, PWR WINDOWSHEAT FUNCTIONING, AC FUNCTIONINGBACKUP CAMERA, BLUETOOTH, SUBSCRIPTION BASED SATELLITE RADIO, CD PLAYER

In Yard Yes Tires Front 16/32 265/65/18,rear 3/32 265/65/18 Sales Status Green Light MVI 03/25





https://www.maauctions.com/