

Sale Name: October 21, 2025 - Automotive Timed Vehicles & RV's - New Brunswick
LOT 20 - 2016 Mazda Mazda3 i Sport 4dr Sedan 6A



VIN 3MZBM1U73GM246037

Year 2016

Make Mazda

Model Mazda3

Trim Level 2WD

Engine SKYACTIV-G 2.0L I4 155hp 150ft. lbs. PZEV

Transmission AUTOMATIC

Odometer 197 149

Odo Type KM

Color Brown

Declaration Requires Boost

Features (Jardine) Power Windows, Power Locks, Power Mirrors, Cruise Control, Infotainment, Tilt, Alum Rims, Bluetooth, Backup Camera, Cloth Interior, Standard Seating

Air Conditioning / Heat (Jardine) AC Functioning, Heat Functioning

Comments Warning lights: parking brake, low fuel, Vehicle starts with a very hard boost, very weak battery*, windshield cracks, trunk doesn't open with buttons(must be opened from inside trunk)

Location Fredericton NB - Jardine

Unit No. 664351-r

Tires Front 5/32 205/60R16 rear 4/32 205/60R16, right rear wheel is steel, front/rear left wheels missing lug nuts

Sales Status Red Light - Sold AS IS

Plate Date (Jardine) None

Plate Number (Jardine) None

MVI (Jardine) 08/24

Interior Comments (Jardine) Headliner/seats/carpet stains, volume knob missing, manual gear release cover missing, back of front right seat torn, door cards stains/residue, center control buttons sticking bad, steering wheel chrome trim peeling, stickers on inside of door.

Interior Condition (Jardine) Rough

Exterior Comments (Jardine) Front left fender scratches/paint chips, left a pillar dents, front left door scratches/scuffs/residue/door sill scratches, rear left door scratches/paint chips/door sill scratches, rear left fender scratches, rear bumper scratches/paint chips, trunk scratches/rust/dents/residue, right rear fender scratches/scuffs/dents, right rear door scratches/paint chips, front right door scratches/paint chips/door sill dents/scratches, front right fender scratches/paint chips/rust, front bumper scratches/gouges/cracks/missing trim piece, hood scratches/paint chips, windshield cracks, roof dents

Exterior Condition (Jardine) Fair

Description

REQUIRES HARD BOOST

VERY WEAK BATTERY

BANK REPOSSESSION

[CARFAX- OTHER DAMAGE CLAIM \\$11,987.00](#)

VIN 3MZBM1U73GM246037

Year 2016

Make Mazda

Model Mazda3

Trim 2WD

Engine SKYACTIV-G 2.0L I4 155hp 150ft. lbs. PZEV

Transmission AUTOMATIC

Odometer: 197 149, KM

Color Brown

Declaration Requires Boost

Features Power Windows, Power Locks, Power Mirrors, Cruise Control, Infotainment, Tilt, Alum Rims, Bluetooth, Backup Camera, Cloth Interior, Standard Seating

Air Conditioning / Heat AC Functioning, Heat Functioning

Comments Warning lights: parking brake, low fuel, Vehicle starts with a very hard boost, very weak battery*, windshield cracks, trunk doesn't open with buttons(must be opened from inside trunk)

Location Fredericton NB - Jardine

In Yard Yes

Tires Front 5/32 205/60R16 rear 4/32 205/60R16, right rear wheel is steel, front/rear left wheels missing lug nuts

Sales Status Red Light - Sold AS IS

Plate Date None

Plate Number None

MVI 08/24

Interior Comments Headliner/seats/carpet stains, volume knob missing, manual gear release cover missing, back of front right seat torn, door cards stains/residue, center control buttons sticking bad, steering wheel chrome trim peeling, stickers on inside of door.

Interior Condition Rough

Exterior Comments Front left fender scratches/paint chips, left a pillar dents, front left door scratches/scuffs/residue/door sill scratches, rear left door scratches/paint chips/door sill scratches, rear left fender scratches, rear bumper scratches/paint chips, trunk scratches/rust/dents/residue, right rear fender scratches/scuffs/dents, right rear door scratches/paint chips, front right door scratches/paint chips/door sill dents/scratches, front right fender scratches/paint chips/rust, front bumper scratches/gouges/cracks/missing trim piece, hood scratches/paint chips, windshield cracks, roof dents

Exterior Condition Fair

Quantity: 1



<https://www.maauctions.com/>