

Sale Name: October 21, 2025 - Automotive Timed Vehicles & RV's - New Brunswick
LOT 47 - 2012 Toyota RAV4 4WD



VIN 2T3RK4DVXCW080955

Year 2012

Make Toyota

Model RAV4

Trim Level 4WD

Engine 3.5L V6 269hp 246ft. lbs.

Transmission Automatic

Odometer 258 324

Odo Type KM

Color Black

Declaration Carfax Odometer Discrepancy

Features (Jardine) Power Windows, Power Locks, Power Mirrors, Cruise Control, Sunroof, Tilt, Sunroof, Roof Rails / Rack, Alum Rims, CD Player, Cloth Interior, Standard Seating

Air Conditioning / Heat (Jardine) AC Functioning, Heat Functioning

Comments Warning lights: Low fuel.

Location Fredericton NB - Jardine

Tires Front 5/32, rear 3/32

Sales Status Red Light - Sold AS IS

Plate Date (Jardine) None

Plate Number (Jardine) None

MVI (Jardine) 09/25 PEI

Interior Comments (Jardine) Headliner/seats/floor stains.

Interior Condition (Jardine) Good

Exterior Comments (Jardine) Multiple scratches/paint chips, majority of vehicle repainted, front left doorsill rust, rear left fender rust, rear bumper broken, right rear doorsill dents, front bumper broken, windshield crack chips.

Exterior Condition (Jardine) Good

Description

[CARFAX - Collision claim \\$970; Mileage discrepancy noted](#)

VIN 2T3RK4DVXCW080955

Year 2012

Make Toyota

Model RAV4

Trim 4WD

Engine 3.5L V6 269hp 246ft. lbs.

Transmission Automatic

Odometer: 258 324, KM

Color Black

Declaration Carfax Odometer Discrepancy

Features Power Windows, Power Locks, Power Mirrors, Cruise Control, Sunroof, Tilt, Sunroof, Roof Rails / Rack, Alum Rims, CD Player, Cloth Interior, Standard Seating

Air Conditioning / Heat AC Functioning, Heat Functioning

Comments Warning lights: Low fuel.

Location Fredericton NB - Jardine

In Yard Yes

Tires Front 5/32, rear 3/32

Sales Status Red Light - Sold AS IS

Plate Date None

Plate Number None

MVI 09/25 PEI

Interior Comments Headliner/seats/floor stains.

Interior Condition Good

Exterior Comments Multiple scratches/paint chips, majority of vehicle repainted, front left doorsill rust, rear left fender rust, rear bumper broken, right rear doorsill dents, front bumper broken, windshield crack chips.

Exterior Condition Good

Quantity: 1



<https://www.maauctions.com/>