

Sale Name: October 21, 2025 - Automotive Timed Vehicles & RV's - New Brunswick
LOT 73 - 2012 Toyota Prius c Base 4dr Hatchback



VIN JTDKDTB31C1500124

Year 2012

Make Toyota

Model Prius c

Trim Level FWD

Engine 1.5L

Transmission Automatic

Odometer 174 697

Odo Type KM

Color Grey

Declaration Airbag Light On

Features (Jardine) Power Windows, Power Locks, Power Mirrors, Cruise Control, Tilt, CD Player, Bluetooth, Cloth Interior, Standard Seating

Air Conditioning / Heat (Jardine) AC Functioning, Heat Functioning

Comments Left rocker holes

Location Fredericton NB - Jardine

Tires Front 8/32 rear 8/32

Sales Status Red Light - Sold AS IS

Plate Date (Jardine) 06/26

Plate Number (Jardine) JRE 538

MVI (Jardine) 11/25

Interior Comments (Jardine) Headliner/seats stains

Interior Condition (Jardine) Good

Exterior Comments (Jardine) Multiple scratches/paint chips, front left door sill paint bubbling/rust, rear left door sill rust, left rocker rust/holes, right tail light cracks, right rear door dents/door sill rust, front right door dents, hood dents

Exterior Condition (Jardine) Good

Description

[CARFAX- COLLISION CLAIM \\$7,730.60; OTHER DAMAGE RECORDS FOUND](#)

VIN JTDKDTB31C1500124

Year 2012

Make Toyota

Model Prius c

Trim FWD

Engine 1.5L

Transmission Automatic

Odometer: 174 697, KM

Color Grey

Declaration Airbag Light On

Features Power Windows, Power Locks, Power Mirrors, Cruise Control, Tilt, CD Player, Bluetooth, Cloth Interior, Standard Seating

Air Conditioning / Heat AC Functioning, Heat Functioning

Comments Left rocker holes

Location Fredericton NB - Jardine

In Yard Yes

Tires Front 8/32 rear 8/32

Sales Status Red Light - Sold AS IS

Plate Date 06/26

Plate Number JRE 538

MVI 11/25

Interior Comments Headliner/seats stains

Interior Condition Good

Exterior Comments Multiple scratches/paint chips, front left door sill paint bubbling/rust, rear left door sill rust, left rocker rust/holes, right tail light cracks, right rear door dents/door sill rust, front right door dents, hood dents

Exterior Condition Good

Quantity: 1



<https://www.maauctions.com/>