## **Sale Name:** October 21, 2025 - Automotive Timed Vehicles & RV's - New Brunswick LOT 77 - 2017 Dodge Grand Caravan SXT Premium Plus 4dr Mini-Van



VIN 2C4RDGBG9HR640370

**Year** 2017

Make Dodge

Model Grand Caravan

Trim Level FWD

**Engine** 3.6 penastar

**Transmission** Automatic

**Odometer** 184 820

**Odo Type** KM

Color Blue

**Features (Jardine)** Power Windows, Power Locks, Power Mirrors, Power Seats, Cruise Control, Tilt, Roof Rails / Rack, Heated Mirrors, Alum Rims, Subscription Based Satellite Radio, Bluetooth, Backup Camera, Leather Interior, 3rd Row Seating, Stow N Go

Air Conditioning / Heat (Jardine) AC Functioning, Heat Functioning

**Location** Fredericton NB - Jardine

**Tires** Front 7/32 rear 7/32

Sales Status Green Light

Plate Date (Jardine) 11/25

Plate Number (Jardine) NJA 387

**MVI (Jardine)** 09/26

Interior Comments (Jardine) Headliner/seats/floor stains

Interior Condition (Jardine) Good

**Exterior Comments (Jardine)** Multiple scratches/paint chips, left rear fender dents, rear bumper scuffs, right rear taillight broken, right rear fender rust, windshield crack chips

Exterior Condition (Jardine) Good

## **Description**

## CARFAX: CLAIM UNKNOWN \$11,311.00

Vin 2C4RDGBG9HR640370 Year 2017 Make Dodge Model Grand Caravan Trim FWD Engine 3.6 penastar Transmission Automatic

**Odometer** 184 820, KM

Color Blue

**Features** Power Windows, Power Locks, Power Mirrors, Power Seats, Cruise Control, Tilt, Roof Rails / Rack, Heated Mirrors, Alum Rims, Subscription Based Satellite Radio, Bluetooth, Backup Camera, Leather Interior, 3rd Row Seating, Stow N Go

Air Conditioning / Heat (Jardine) AC Functioning, Heat Functioning

**Location** Fredericton NB - Jardine

In Yard Yes

Tires Front 7/32 rear 7/32 Sales Status Green Light

Plate Date 11/25

Plate Number NJA 387

**MVI** 09/26

**Interior Comments** Headliner/seats/floor stains

Interior Condition Good

**Exterior Comments** Multiple scratches/paint chips, left rear fender dents, rear bumper scuffs, right rear taillight broken, right rear fender rust, windshield crack chips

Exterior Condition Good

Quantity: 1



https://www.maauctions.com/