

Sale Name: October 21, 2025 - Automotive Timed Vehicles & RV's - New Brunswick
LOT 30 - 2010 Dodge Ram 1500 4x4 TRX4 Off Road 4dr Quad Cab 6.3 ft. SB Pickup



VIN 1D7RV1GT3AS191407

Year 2010

Make Dodge

Model Ram 1500

Trim Level 4x4

Body Subtype Extended Cab

Engine HEMI 5.7L V8 390hp 407ft. lbs.

Transmission Automatic

Odometer 352 315

Odo Type KM

Color Silver

Declaration Engine Light On

Features (Jardine) Power Windows, Power Locks, Power Mirrors, Power Seats, Cruise Control, Tilt, Heated Mirrors, Alum Rims, Hitch, CD Player, Subscription Based Satellite Radio, Bluetooth

Air Conditioning / Heat (Jardine) AC Functioning, Heat Functioning

Rear Compartment / Pickup Bed (Jardine) Box Liner

Comments Warning lights: Engine light, low tire pressure, oil change due.

Location Fredericton NB - Jardine

Sales Status Red Light - Sold AS IS

Plate Date (Jardine) 05/26

Plate Number (Jardine) CYP 713

MVI (Jardine) 08/26

Interior Condition (Jardine) Good

Exterior Comments (Jardine) Tailgate dents/rust/paint chips/paint missing/rust stains, rear bumper rust, hitch rust, rearview window stickers and glue residue, right rear wheel well paint bubbling/scratches/rust, front fender rust, front left door sill rust

Exterior Condition (Jardine) Fair

Description

***Vehicle runs rough, vehicle loud - possible exhaust leak**

CLEAN CARFAX

Vin 1D7RV1GT3AS191407

Year 2010

Make Dodge

Model Ram 1500

Trim 4x4, Extended Cab

Engine HEMI 5.7L V8 390hp 407ft. lbs.

Transmission Automatic

Odometer: 352 315, KM

Color Silver

Declaration Engine Light On

Features Power Windows, Power Locks, Power Mirrors, Power Seats, Cruise Control, Tilt, Heated Mirrors, Alum Rims, Hitch, CD Player, Subscription Based Satellite Radio, Bluetooth

Air Conditioning / Heat AC Functioning, Heat Functioning

Rear Compartment / Pickup Bed Box Liner

Location Fredericton NB - Jardine

Comments Warning lights: Engine light, low tire pressure, oil change due.

In Yard Yes

Sales Status Red Light - Sold AS IS

Plate Date 05/26

Plate Number CYP 713

MVI 08/26

Interior Condition Good

Exterior Comments Tailgate dents/rust/paint chips/paint missing/rust stains, rear bumper rust, hitch rust, rearview window stickers and glue residue, right rear wheel well paint bubbling/scratches/rust, front fender rust, front left door sill rust

Exterior Condition Fair

Quantity: 1



Family Owned & Operated Since 1971

<https://www.maauctions.com/>