

Sale Name: October 21, 2025 - Automotive Timed Vehicles & RV's - New Brunswick
LOT 32 - 2014 GMC Terrain AWD



VIN 2GKFLXEK8E6141342

Year 2014

Make GMC

Model Terrain

Trim Level AWD

Engine Ecotec 2.4L I4 182hp 172ft. lbs.

Transmission Automatic

Odometer 211,204

Odo Type KM

Color Grey

Declaration Engine Light On

Features (Jardine) Power Windows, Power Locks, Power Mirrors, Power Seats, Cruise Control, Sunroof, Infotainment, Tilt, Sunroof, Roof Rails / Rack, Heated Seats, Heated Mirrors, Alum Rims, CD Player, Subscription Based Satellite Radio, Bluetooth, Backup Camera, Leather Interior, Standard Seating

Air Conditioning / Heat (Jardine) AC Functioning, Heat Functioning

Location Fredericton NB - Jardine

Tires Front 8/32 rear 7/32

Sales Status Red Light - Sold AS IS

Plate Date (Jardine) 03/26

Plate Number (Jardine) JIB 377

MVI (Jardine) 01/26 unverified

Interior Comments (Jardine) Headliner/seats/floor stains

Interior Condition (Jardine) Good

Exterior Comments (Jardine) Multiple scratches/paint chips, front left fender rust, front left door rust, rear left fender rust, right rear fender rust, right rear door rust, front right doorsill dents, front right fender rust, windshield chips

Exterior Condition (Jardine) Good

Description

[CLEAN CARFAX](#)

VIN 2GKFLXEK8E6141342

Year 2014

Make GMC

Model Terrain

Trim AWD

Engine Ecotec 2.4L I4 182hp 172ft. lbs.

Transmission Automatic

Odometer: 211,204, KM

Color Grey

Declaration Engine Light On

Features Power Windows, Power Locks, Power Mirrors, Power Seats, Cruise Control, Sunroof, Infotainment, Tilt, Sunroof, Roof Rails / Rack, Heated Seats, Heated Mirrors, Alum Rims, CD Player, Subscription Based Satellite Radio, Bluetooth, Backup Camera, Leather Interior, Standard Seating

Air Conditioning / Heat AC Functioning, Heat Functioning

Location Fredericton NB - Jardine

In Yard Yes

Tires Front 8/32 rear 7/32

Sales Status Red Light - Sold AS IS

Plate Date 03/26

Plate Number JIB 377

MVI 01/26 unverified

Interior Comments Headliner/seats/floor stains

Interior Condition Good

Exterior Comments Multiple scratches/paint chips, front left fender rust, front left door rust, rear left fender rust, right rear fender rust, right rear door rust, front right doorsill dents, front right fender rust, windshield chips

Exterior Condition Good

Quantity: 1



<https://www.maauctions.com/>