Sale Name: October 23 - 24, 2025 - Unreserved Equipment, Trucks, Trailers, Light Vehicles & RV Live 2 Day Auction

LOT 287 - 2017 Ram 1500 Tradesman



VIN 1C6RR7FTXHS562275

Year 2017 Make Ram

Model 1500

Trim Level Tradesman

Body Subtype Extended Cab

Engine HEMI 5.7L V8 395hp 410ft. lbs.

Transmission Automatic

Odometer 478 486

Odo Type KM

Color White

Declaration Engine Light On

Features (Jardine) Power Windows, Power Locks, Power Mirrors, Cruise Control, Tilt, Heated Mirrors, Alum Rims, Hitch, Subscription Based Satellite Radio, Cloth Interior, Standard Seating

Air Conditioning / Heat (Jardine) AC Functioning, Heat Functioning

Comments Warning Lights: engine light, low windshield washer fluid, gas cap.

Location Fredericton NB - Jardine

Tires Front 10/32, rear 11/32

Sales Status Red Light - Sold AS IS

Plate Date (Jardine) 01/25

Plate Number (Jardine) CTI 680

MVI (Jardine) 01/27

Interior Comments (Jardine) Carpet/seat/headliner stains, driver seat tear.

Interior Condition (Jardine) Good

Exterior Comments (Jardine) Multiple scratches/paint chips, left A puller rust/ windshield strip gouged front left fender rust/dent/ appears to been painted, front left door rust/dents, rear left door paint missing/rusting/appears to been painted, rear left fender dented/rust/ plastic trim melted, left rocker rust, tail gate both light cracked/broken, rust/dents/plastic trim broken/melted, bed melted/fire damage, tool box has fire damage/warped. Rear bumper dented/rusting. Rear right fender burnt/ paint peeling/dents, right c puller burnt rear right door paint peeling/paint cracked/ melted handle. Right rocker rusting, hood paint cracking/bubbling. Front bumper plastic trim cracked, roof rusting.

Exterior Condition (Jardine) Rough

Description

Vin 1C6RR7FTXHS562275 Year 2017 Make Ram Model 1500

Trim Tradesman, Extended Cab

Engine HEMI 5.7L V8 395hp 410ft. lbs.

Transmission Automatic **Odometer:** 478 486, KM

Color White

Declaration Engine Light On

Features Power Windows, Power Locks, Power Mirrors, Cruise Control, Tilt, Heated Mirrors, Alum Rims, Hitch, Subscription Based Satellite Radio, Cloth Interior, Standard Seating

Air Conditioning / Heat AC Functioning, Heat Functioning

Location Fredericton NB - Jardine

Comments Warning Lights: engine light, low windshield washer fluid, gas cap.

In Yard Yes

Tires Front 10/32 , rear 11/32 **Sales Status** Red Light - Sold AS IS

Plate Date 01/25

Plate Number CTI 680

MVI 01/27

Interior Comments Carpet/seat/headliner stains, driver seat tear.

Interior Condition Good

Exterior Comments Multiple scratches/paint chips, left A puller rust/ windshield strip gouged front left fender rust/dent/ appears to been painted, front left door rust/ dents, rear left door paint missing/rusting/appears to been painted, rear left fender dented/rust/ plastic trim melted, left rocker rust, tail gate both light cracked/broken, rust/dents/plastic trim broken/melted, bed melted/fire damage, tool box has fire damage/warped. Rear bumper dented/rusting. Rear right fender burnt/paint peeling/ dents, right c puller burnt rear right door paint peeling/paint cracked/melted handle. Right rocker rusting, hood paint cracking/bubbling. Front bumper plastic trim cracked, roof rusting.

Exterior Condition Rough

Quantity: 1



